

# Table of Contents

List of Figures and Tables	v
List of Acronyms	ix
Executive Summary	xi
1 Introduction	
1.1 Purpose	
1.2 Team Composition	
1.3 Methodology	
1.4 Presentation of Findings	
2 Background on Tornadoes and History of the Storm	
2.1 The Fujita Scale and Tornado Probability	
2.2 Tornadoes and Associated Damage	
2.3 Background of the Event	
3 General Assessment and Characterization of Damage	
3.1 Property Protection	
3.1.1 Overview of Buildings Evaluated	
3.1.1.1 Residential Buildings	
3.1.1.2 Non-Residential Buildings	
3.1.2 Load Path and Increased Loads	
3.2 Wind-Borne Debris	
3.2.1 Missile Types and Sizes	
3.2.2 Wind-Borne Missile Quantity	
3.3 Personal Protection and Sheltering	
3.4 Local, State, and Federal Regulation	
3.4.1 Oklahoma	
3.4.2 Kansas	
4 Observations on Residential Property Protection	
4.1 Single Family Conventional Construction	
4.1.1 Load Paths	
4.1.2 Roof and Wall Sheathing	
4.1.3 Connections	
4.1.4 Increased Load	
4.1.5 Roof Coverings	
4.1.6 Wall Coverings	
4.1.7 Garage Door	
4.1.8 Windows and Doors	
4.1.9 Masonry	

- 4.2 Multi-Family Construction
- 4.3 Manufactured Housing
- 5 Observations on Non-Residential Property Protection
  - 5.1 Load Path
    - 5.1.1 Tilt-up with Steel Joists
    - 5.1.2 Load Bearing Masonry with Steel Joists
    - 5.1.3 Steel Frame with Masonry Infill Walls
    - 5.1.4 Light Steel Frame Buildings
    - 5.1.5 Laminated with Wood Frame
    - 5.1.6 Masonry with Pre-cast Floors
  - 5.2 Increased Load
    - 5.2.1 Tilt-up Precast Walls with Steel Joists
    - 5.2.2 Load Bearing Masonry with Steel Joists
    - 5.2.3 Steel Frame with Pre-cast Hollow Core
  - 5.3 Non-Residential Roof and Wall Coverings
    - 5.3.1 Roof Coverings
    - 5.3.2 Wall Coverings
    - 5.3.3 Laminated Glass
    - 5.3.4 Garage Doors, Exterior Doors and Windows
- 6 Observations on Personal Protection and Sheltering
  - 6.1 Shelters
    - 6.1.1 Types of Shelters
    - 6.1.2 Use of Shelters
    - 6.1.3 Maintenance Issues with Shelters
    - 6.1.4 Shelter Accessibility
    - 6.1.5 Shelter Ventilation
    - 6.1.6 Shelter Location
  - 6.2 Other Places of Refuge
    - 6.2.1 Refuge in Residences
    - 6.2.2 Refuge in Non-Residential Buildings
- 7 Preliminary Conclusions
  - 7.1 Residential Property Protection
    - 7.1.1 Single and Multi-family Homes
      - 7.1.1.1 Load Path and Structural Systems
      - 7.1.1.2 Increased Load Caused by Breach of Envelope
      - 7.1.1.3 Masonry
    - 7.1.2 Manufactured Housing
      - 7.1.2.1 Foundations
      - 7.1.2.2 Anchors
      - 7.1.2.3 Strapping
      - 7.1.2.4 Modules (Superstructure)
  - 7.2 Non-residential
    - 7.2.1 Load Path
    - 7.2.2 Increased Load Caused by Breach of Envelope
    - 7.2.3 Roof and Wall Coverings

7.3	Personal Protection and Sheltering
7.3.1	Residential Shelters
7.3.2	Group Shelters
7.3.3	Community Shelters
7.3.4	Other Places of Refuge
8	Preliminary Recommendations
8.1	General Recommendations
8.2	Property Protection
8.2.1	Residential and Non-Residential Buildings
8.2.2	Codes and Regulations, Adoption and Enforcement
8.2.3	Voluntary Actions
8.3	Personal Protection
8.3.1	Residential Sheltering
8.3.2	Group and Community Sheltering
8.3.3	Places of Refuge
9	References (Not included at this time)
Appendixes	
Appendix A	Members of the Building Performance Assessment Team
Appendix B	Acknowledgements
Appendix C	National Performance Criteria for Tornado Shelters
Appendix D	Taking Shelter from the Storm
Appendix E	List of Useful Websites



# List of Figures and Tables

Figure 1-1	BPAT meeting with State of Kansas and local government officials
Figure 1-2	BPAT meeting with Mid West City fire official
Table 1-1	BPAT damage assessment
Figure 2-1	Probability of tornado occurrence in the United States
Figure 2-4	Outbreak map of May 3, 1999 tornadoes in Oklahoma
Figure 2-5	Radar reflectivity map showing hook echo
Figure 2-6	Radar cross-section through F5 tornado
Figure 2-7	Outbreak map of May 3, 1999 tornadoes in Kansas
Table 2-1	Fujita Scale
Figure 3-1	Continuous load path for a wood frame building
Figure 3-2	Building failure due to inward wind and uplift
Figure 3-3	Wind uplift on residential home
Figure 3-4	Increased loads due to breach in envelope
Figure 3-5	Hip roof failure due to internal pressure and leeward wind forces
Figure 3-6	Failure of gable wall due to suction forces of leeward wall
Figure 3-7	Failure of exterior wall and roof due to increased internal pressure
Figure 3-8	EIFA and metal component damage
Figure 3-9	URM wall failure due to inflow winds
Figure 3-10	Failure of steel frame structural system with masonry infill walls
Figure 3-11	Broken window due to small missile
Figure 3-12	Picture of moderate sized missile
Figure 3-13	Large, high energy missile
Figure 3-14	Examples of board missiles
Figure 3-15	Windborne missile striking house
Figure 3-16	Vertical striking missile
Figure 3-17	Board missile penetrating brick veneer
Figure 3-18	Board missile penetrating refrigerator
Figure 3-19	Power pole missile
Figure 3-20	Displaced large propane tank due to wind
Figure 3-21	Steel deck missile
Figure 3-22	Tree missile
Figure 3-23	Quantity of flying debris
Figure 3-24	Polyisocyanurate roof insulation on top of the school roof
Figure 3-25	Close-up of polyisocyanurate roof insulation
Figure 3-26	Missile striking roof
Figure 3-27	Missiles striking exterior wall of house
Figure 3-28	Missiles striking interior wall of house
Figure 3-29	Underground residential shelter
Figure 4-1	Platform construction

Figure 4-2	Lateral load transfer
Figure 4-3	Failed stapling of boards to rafters
Figure 4-4	Staggering joints in sheathing application
Figure 4-5	Shear load force offset by wall sheathing
Figure 4-6	Wall failure due to inadequate lateral load resistance
Figure 4-7	CAPTION NEEDED
Figure 4-8	Roof-framing to wall failure
Figure 4-9	Top plate to supporting stud connection failure
Figure 4-10	Wall framing to sill plate failure
Figure 4-11	Stud wall and sole plate to floor failure
Figure 4-12	Sill plate foundation failure at wall
Figure 4-13	Sill plate to foundation failure
Figure 4-14	Asphalt shingles on roof
Figure 4-15	T-lock shingles on roof
Figure 4-16	Vinyl siding damage
Figure 4-17	Vinyl siding damage
Figure 4-18	Garage door failure under suction load
Figure 4-18A	Typical double-wide garage door elevation
Figure 4-18B	Plan view of typical garage door
Figure 4-18C	Reinforced horizontal latch system for garage door
Figure 4-18D	Garage door failure at track
Figure 4-19	Partial schematic of subdivision
Figure 4-20	Partial roof loss versus total loss under internal pressure
Figure 4-21	ADD CAPTION
Figure 4-22	Garage and roof failure
Figure 4-23	Garage door failure
Figure 4-24	Roof uplift
Figure 4-25	Missile penetrated door
Figure 4-26	ADD CAPTION
Figure 4-27	Roof failure
Figure 4-28	Interior of home with roof failure
Figure 4-29	TEMPORARY PLACE HOLDER
Figure 4-30	Failure of masonry construction
Figure 4-31	Brick masonry failure
Figure 4-32	Failure of masonry wall
Figure 4-33	Failure of brick veneer, close-up
Figure 4-34	Inadequate bond of mortar to galvanized brick ties
Figure 4-35	Inadequate bonding of mortar to brick and ties
Figure 4-36	Failure of masonry veneer wall
Figure 4-37	Failure of masonry veneer wall
Figure 4-38	Failure of masonry veneer wall
Figure 4-39	Failure of masonry veneer wall
Figure 4-40	Failure of chimney onto home
Figure 4-41	Failure of chimney, close-up
Figure 4-42	Failure of chimney onto home
Figure 4-43	Failure of masonry veneer, multifamily
Figure 4-44	Failure of masonry veneer, multifamily
Figure 4-45	Failure of masonry veneer, multifamily

Figure 4-46	Failure of chimney
Figure 4-47	Failure of chimney
Figure 4-48	Destroyed chassis
Figure 4-49	Failed straps
Figure 4-50	Displaced chassis
Figure 4-51	Pulled anchor
Figure 4-52	Pulled and bent anchor
Figure 4-53	Strap failure
Figure 4-54	Roof Uplift
Figure 4-55	ADD CAPTION
Figure 4-56	View of displaced chassis foundation
Figure 4-57	View of removed chassis
Figure 4-58	Laterally shifted manufactured home
Figure 4-59	Pulled anchors and lateral displacement
Figure 4-60	Strap and lateral shifting
Figure 4-61	Shifted manufactured home
Figure 5-1	Failure of critical connections in load path
Figure 5-2	Failure of tilt-up precast concrete walls
Figure 5-3	Damage displaying separation of bond beams
Figure 5-4	Broken welds and no effective vertical reinforcement
Figure 5-5	Blown off metal roof decking
Figure 5-6	Foundation and wall attachments
Figure 5-7	Column anchors exhibiting ductile failure
Figure 5-8	Column anchors withdrawn from concrete foundation
Figure 5-9	Stroud Regional Outlet Mall
Figure 5-10	Loss of church roof
Figure 5-11	Motel damage from violent tornado vortex
Figure 5-12	Out of plane buckling of the main girder
Figure 5-13	Collapsed roof structure and exterior
Figure 5-14	Blown off roof over school auditorium
Figure 5-15	Exterior of an undamaged reinforced concrete wall
Figure 5-16	Failure of tilt-up concrete wall
Figure 5-17	Top of failed tilt up wall
Figure 5-18	Top of failed tilt up wall
Figure 5-19	Failed roof system with intact tilt up concrete walls
Figure 5-20	Damage to non-reinforced masonry walls
Figure 5-21	Hollow core plank formed on second floor
Figure 5-22	Failure of power driven anchors
Figure 5-23	CAPTION NEEDED
Figure 5-24	Collapsed metal clad wall covering
Figure 5-25	Penetration of laminated glass
Figure 5-26	Roof and wall failure
Figure 5-27	Structural damage due to breach in envelope
Figure 6-1	Above ground in residence shelter
Figure 6-2	Surrounding damage near shelter
Figure 6-3	Entrance to ICF shelter

Figure 6-4	Precast concrete storm cellar
Figure 6-5	Storm cellar constructed of steel sheets and concrete cover
Figure 6-6	Community shelter at manufactured home park
Figure 6-7	Above ground in residence shelters
Figure 6-8	Entrance to manufacturing plant group shelter
Figure 6-9	Group shelters at manufactured home development
Figure 6-10	Manufactured home development community shelter
Figure 6-11	Community shelter in school gymnasium
Figure 6-12	Unmaintained underground shelter door
Figure 6-13	Failed wooden door of below ground shelter
Figure 6-14	Inadequate shelter door locking device
Figure 6-15	Ballast roof covering on community shelter
Figure 6-16	Stairway to manufactured home community shelter
Figure 6-17	Stairway access to group shelter
Figure 6-18	Heavy gauge ventilation pipe for below ground shelter
Figure 6-19	Basement windows to home vulnerable to debris
Figure 6-20	Below ground shelter susceptible to water runoff
Figure 6-21	Remains of interior core room
Figure 6-22	Remaining interior core of house
Figure 6-23	Interior bathroom of damaged home
Figure 6-24	Missile penetrating exterior wall
Figure 6-25	Missile piercing wall stud
Figure 6-26	Bathroom located along exterior wall
Figure 6-27	Second story damage
Figure 6-28	Damaged manufactured homes
Figure 6-29	Locker room – designated place of refuge
Figure 6-30	School hallway
Figure 6-31	Unsafe corridor place of refuge in school
Figure 6-32	Unsafe corridor place of refuge in school
Figure 6-33	Unsafe corridor place of refuge in school
Figure 6-34	EIFS wall system torn from studs
Figure 6-35	Collapsed non-reinforced interior CMU walls in school
Figure 6-36	Blown off roof and ceiling over interior bathroom



# List of Acronyms

ADA	Americans with Disabilities Act
ASCE	American Society of Civil Engineers
ASTM	American Society for Testing and Materials
BOCA	Building Officials and Code Administrators, International
BPAT	Building Performance Assessment Team
CABO	Council of American Building Officials
COHBA	Central Oklahoma Home Builders Association
CMU	Concrete Masonry Unit
EIFS	Exterior Insulating Finishing System
EPDM	Ethylene Propylene Diene Monomer
EPS	Expanded Polystyrene System
FEMA	Federal Emergency Management Agency
GIS	Geographic Information System
HUD	Department of Urban Development
HVAC	Heating, Ventilation, and Air Conditioning
ICBO	International Conference of Building Officials
MCHSS	Manufactured Home Construction and Safety Standards
NBC	National Building Code
NCSBCS	National Conference of States on Building Codes and Standards
NFIP	National Flood Insurance Program
NFPA	National Fire Protection Association
NOAA	National Oceanic Atmospheric Administration
NSSL	National Severe Storms Laboratory
OSB	Oriented Strand Board
SBCCI	Southern Building Code Congress International
UBC	Uniform Building Code
URM	Un-reinforced Masonry



# Executive Summary

On the evening of May 3, 1999, an outbreak of tornadoes tore through parts of Oklahoma and Kansas, in areas that are considered part of "Tornado Alley", leveling entire neighborhoods and killing 49 people. The storms that spawned the tornadoes moved slowly, contributing to the development and redevelopment of individual tornadoes over an extended period of time.

On May 10, the Federal Emergency Management Agency's (FEMA's) Mitigation Directorate deployed a Building Performance Assessment Team (BPAT) to Oklahoma and Kansas to assess damage caused by the tornadoes. The team was composed of national experts including FEMA Headquarters and Regional Office engineers and staff; a meteorologist; architects; planners; wind engineers; structural engineers; and forensic engineers. The mission of the BPAT was to assess the performance of buildings affected by the tornadoes, investigate losses, and describe the lessons learned. This report presents the BPAT's observations, conclusions, and recommendations, which are intended to help communities, businesses, and individuals reduce future injuries and the loss of life and property resulting from tornadoes and other high-wind events. It is not the intent of this report to reclassify the strength of the May 3 tornadoes or the ratings of the damage observed, or to debate the magnitude of the wind speeds associated with those tornadoes. Rather, the intent is to clearly define some basic concepts associated with tornadoes and tornado damage that will be referred to throughout this report.

The observations, conclusions, and recommendations in this report are grouped to address issues concerning (1) residential property protection, (2) non-residential property protection, and (3) personal protection and sheltering. The BPAT's findings are correlated with the Fujita damage scale, which ranks tornadoes according to the damage they cause, and general tornado intensity (Table 1-1).

Tornadoes are extremely complex wind events that cause damage ranging from minimal or minor to absolute devastation. For the purposes of this report, tornado intensity is simplified and referred to by three categories: moderate, severe, and violent. In a violent tornado, the most severe damage occurs. Typically, all buildings are destroyed and trees are uprooted, debarked, and splintered. In a severe tornado, buildings may also be destroyed, but others may suffer less severe damage, such as the loss of exterior walls, the roof structure, or both. Even when buildings in this area lose their exterior walls and roofs, interior rooms may survive. In moderate tornadoes, damage to buildings primarily affects roofs and windows. Roof damage ranges from loss of the entire roof structure to the loss of all or part of the roof sheathing or roof coverings. Typically, many of the windows in buildings will be broken by wind-borne debris.

During the field investigation, the BPAT investigated buildings to identify successes and failures that occurred during the tornadoes. Building failures were identified as being directly struck by the vortex or core of the tornado, affected by winds outside the vortex of the tornado, or out on the extreme edge or periphery of the tornado path. Considerable damage to all types of structures throughout Oklahoma and Kansas was observed. Failures occurred when extreme winds produced forces on the buildings that they were not designed to withstand. Failures also occurred when wind-borne debris penetrated the building envelope, allowing wind inside the building that again produced forces on the buildings that they were not designed to withstand. Additional failures observed were attributed to improper construction techniques

and poor selection of construction materials. It was a goal of the BPAT to determine if any of the damage observed to both residential and non-residential buildings was preventable.

Most residential construction in Oklahoma and Kansas is currently required to be designed per the 1995 Council of American Building Officials (CABO) One and Two Family Dwelling Code. Although some amendments have been adopted by local municipalities, this code does not incorporate wind speed design parameters used by the newer 1997 Uniform Building Code (UBC) and 1996 National Building Code (NBC). Furthermore, engineering standards such as the American Society of Civil Engineers (ASCE) 7-95 and 7-98 design standard provide better structural and non-structural design guidance for wind loads than these newer codes. Although designing for tornadoes is not specifically addressed in any of these newer codes or standards, constructing residential homes to these codes and standards would improve the strength of the built environment. The BPAT concluded that building to these codes and standards would have led to reduced or minimized damage in areas that were affected by the inflow winds of all tornadoes and reduced the damage observed where moderate tornadoes impacted residential construction.

The BPAT concluded that the best means to reduce loss of life and minimize personal injury during any tornadic event is to take refuge in specifically designed tornado shelters. Although improved construction may reduce damage to buildings and provide for safer buildings, an engineered shelter is the best means of providing individuals near absolute protection.

The BPAT developed recommendations for reducing future tornado damage to property and providing personal protection. Broad recommendations include the following:

- Proper construction techniques and materials must be incorporated into the construction of residential buildings to reduce their vulnerability to damage during extreme wind events. Existing construction techniques proven to minimize damage in wind-prone areas are not always being utilized in areas that are subject to tornadoes.
- Construction should be regulated and inspected to ensure that residential buildings meet the most current building code requirements, including those regarding structural seismic issues.
- For engineered buildings, the engineer should review connections to ensure adequate capacity for moderate to severe uplift and lateral loads that may be in excess of loads based on the building codes currently in effect.
  - Cities and appropriate local governments should adopt the 1997 UBC or 1996 NBC as the model building codes.
  - Cities and appropriate local governments not already using the 1995 CABO One- and Two-Family Dwelling Code should do so immediately.
  - The International Building Code (IBC) and the International Residential Code (IRC) should be adopted upon their release in 2000.
  - Shelters are the best means of providing near absolute protection for individuals who are attempting to take refuge during a tornado.
  - All shelters should be designed and constructed in accordance with either FEMA 320 or The National Performance Criteria for Tornado Shelters

